# Xanita

X-Board Cutting Sequence   24th July 2007

Designers of cut files should follow the principles of the cutting sequence shown below and programme their cut files accordingly.

This sequence will avoid the interruption of a cutter as the possibility of a build up of paper on the cutting blade (or local tear when the "V" Cuts cross) is minimised when this sequence is followed.

"V" Cuts Down the Length of the Board 2nd

Straight Cuts 3rd

"V" Cuts Across the Board 1st

1st   "V" Cuts across X-Board
2nd   "V" Cuts down the length of X-Board
3rd   Straight Cuts where applicable

DIGITAL COLOR INK, LLC

www.digitalcolorink.com
Office: 301-937-8772
Toll: 877-616-8600